

NTCRAs Submunitions Area Controlled Burn/Remote Equipment Surface Clearance & Cayo La Chiva Underwater MEC Removal Vieques, PR

Presented By


Daniel Hood

Naval Facilities Engineering Command (NAVFAC)

Atlantic

Vieques Location Map





Objectives




- Overview of two major milestone Removal Actions on the Vieques Project
 - NTCRA for the Surface Clearance of the Submunitions Area
 - o Controlled Burn with Air monitoring
 - Remote Equipment utilization
 - o Final Surface Clearance
 - NTCRA UXO 16 Adjacent to Cayo La Chiva
 - Biological Work
 - MEC removal and disposal
- Lessons Learned



Cayo La Chiva NTCRA






History



- 2010 Munitions items found adjacent to Blue Beach (a public beach)
- Navy EOD Team Conducted a visual inspection of the waters near Blue Beach and Cayo La Chiva
 - o Identified 9 possible MEC items
- 2011 Site Inspection of Cayo La Chiva
 - o Identified 5 five inch rockets
 - Several Smoke canisters
 - Conducted Demo on island
 - Installed LUC

Signs at all public access points Signs on Cayo La Chiva Buoys around Cayo La Chiva



Initiated an Investigation of Blue Beach

NTCRA Activities



- Conducted from June 19 through 23, 2017
- Team included:
 - Munitions Response divers to locate, excavate, identify, and properly handle items recovered
 - Scientific divers to ensure threatened corals and other sensitive species/habitats were avoided
 - Full-time security boat to maintain exclusion zones from recreational boaters and swimmers
 - Support boat for regulatory oversight
 - Playa La Chiva was closed during operations




Photo by CH2MHILL

Dive Operations





Pre-Dive Operations: Safety Brief

Target Location: Utilizing Underwater Navigation System



Biological Work





- Pre Removal Biological Survey:
 - Identify Protected Coral Species and Non Protected Corals that will be affected
- During the Removal:
 - Monitor Protected Species
 - o Relocate all Corals



Photos by CH2MHILL

Recovery Operations










Findings



- Location 1 Cylindrical rock
- Location 2 5-inch rocket
 - Two ESA-listed corals found within 5 and 10 ft
- Location 3 5-inch rocket
 - Three ESA-listed corals found within 6, 10, and 15 ft
- Location 4 Cylindrical rock
- Location 5 Rock
- Location 6 MD fragment
- Location 7 5-inch rocket
- Location 8 5-inch rocket
- Location 9 5-inch rocket






Classification of Items







Demolition





- Items Appeared to be empty due to large visible rust holes.
- Attempted to perforate items to visibly inspect.

Demolition





Lessons Learned/Summary



- Just because it looks like a rocket doesn't mean it is a rocket.
 - Never conduct just a visual underwater survey
 - Once you identify an item as MEC underwater it is very hard to convince the regulators otherwise.
- EVEN THE EXPERTS CAN BE WRONG!
- All underwater work is at the Mercy of Mother Nature.








UXO 4 Submunitions Area TCRA Update

Vieques Technical Subcommittee Meeting February 28, 2017

Submunitions Area





Munitions Identified in Submunitions Area












History





- 75 acres of the highest density area remain
- Mixed munitions types
- Rough Terrain
- Thick vegetation
- Controlled Burn (tested)Variance?
- Remote Removal tested
- Public Opinion

NTCRA Removal Process



Step One

- Remote cutting of vegetation
 - Could not hand cut due to safety
 - Cutting required to burn

Step Two

- Remote Removal of Bombs
 - Equipment capable of moving MEC (from 20 mm to 2,000 lb bombs)
 - Personnel located outside of fragmentation arcs
 - No manual handling of MEC or equipment for securing MEC
 - Large Item Demo conducted





NTCRA Removal Process






October, 2017 Burn





Air Monitoring Locations





Air Monitoring Constituents



Particulate matter

- PM₁₀ (particulate matter 10 microns or smaller in size)
- PM_{2.5} (particulate matter 2.5 microns or smaller in size)

Carbon monoxide

Explosives

НМХ	Nitrobenzene	1,3,5-Trinitrobenzene	2,6-Dinitrotoluene
RDX	1,3-Nitrobenzene	2,4-Dinitrotoluene	2,4,6-Trinitrotoluene

Metals

Arsenic	Copper	Iron	Mercury	Phosphorus
Cadmium	Chromium	Lead	Nickel	Tin

NTCRA Removal Process



- Step Five
 - MEC Surface Clearance
 - · QA
- Step Six
 - DEMO
- Step Seven
 - Final Surface
 - · QA





5 Events Cycles




- Five controlled burns to date
 - January 2015, October 2016, November 2016, March 2017, June 2017
 - Hurricane Maria Delay
 - 17 acres cleared of the 75
 - 5,949 MEC items
 - 4,250 Submunitions
 - NO Air monitoring exceedances
- 18,165 submunitions have been removed from the LIA

Lessons Learned/Summary



- Flexibility is the Key
 - All plans change
 - Fire does what it wants
 - Mother Nature!!!
- Remote does not equal Fast
 - Cycle time





Knowledge Check



- Please take 10 minutes to complete a 250 character summary of my presentation to be graded at Happy Hour!
 - Paper and pencil are available in your hotel room.

Key Topics to include:

- What types of Plans are needed prior to conducting a Dive?
- Are Endangered Species important?
- o Are the experts always correct?
- Should we be flexible on removals?
- o Is safety important?
- Is remote controlled equipment cheap?
- o Is Mother Nature Predictable?
- Who should you call if you need MEC technical assistance?



Photos courtesy of Jim Brantley LANT PAO

NAVFAC Atlantic Points of Contact



Dan Waddill dan.waddill@navy.mil (757)322-4983

Daniel Hood daniel.r.hood@navy.mil (757) 322-4630

Kevin Cloe kevin.cloe@navy.mil (757) 322-4736 Tim Wenk tim.wenk@navy.mil (757)322-4208

Stacin Martin
Stacin.martin@navy.mil
(757)322-4780

Mike Green
Mike.green@Navy.mil
(757)322-8108